



This side is facing outward






This side is facing inward

With all LEDS, make sure the longer wire is going into the + side





You can use 7 or 8 pins here. The last pin is just in case you can't find 7 pin connectors should you choose to try those types of connections. If you don't want to use a header pin, you can just solder the wires directly to the board.

220 Ohm

Resistor

220 Ohm

Resistor



This side is facing outward

